



Safety_Bulletin

To: Larry Allen, Republic Services
Phil Hoffman, Field Service Representative, LabriePlus
Carl Pezold, Directors of Field Services, LabriePlus

From: LabriePlus Customer Support Center

Subject: Body Hoists Installed On Specific Units

The body hoists installed on specific Labrie units have to be replaced with new ones. Arrangements have already been made by Phil Hoffman, the North East LabriePlus Field Service Representative.

For safety reasons, specific body hoists shall be replaced with new ones that are known to be built according to specifications. Gland nuts may not have been locked in place with a dowel pin as it should have. A small production lot of body hoist cylinders has been identified and could potentially have "missing dowel pins" on gland nuts.

Serious injuries and/or death could result in the case of a body hoist failure due to gland nuts that could possibly unscrew on their own. The hoists could uncouple. The replacement body hoists shall be installed within (30) days from the date of publication of this bulletin.

List of concerned units:

EX10112VDA
EX10112VDD

Warranty coverage per unit:

- Three (3) hours of labor
- Replacement body hoist
- Ground freight

The body hoist replacement will be covered under warranty. The body hoists that will be removed shall be returned to LabriePlus USA.

**If you have any queries or require any further information please contact
The Labrie Service Department at 1-800-231-2771.**