

## Parts & Service Bulletin

To: All Distributors

**Regional Sales Managers and National Sales Manager** 

From: Parts Center/Technical Support

Model: All

Subject: New Solenoid

Please note that the main power relay, part number ELR00825, has been replaced. The new relay, part number ELR00825-01, is a direct replacement and supersedes the previous version which is no longer available.

The ELR00825-01 relay has a PVC coating to provide enhanced protection from the elements when mounted in an exterior location, and is a direct replacement with no modifications required. When replacing an exterior mounted relay, the following items should be observed:

- Clean the harness connectors, to ensure good contact with the relay posts.
- Clean the Relay mounting area to obtain good contact between the relay base and the mounting bracket/frame.
- Install a weatherproof lubricant/sealant (dielectric grease) to the exposed wire contacts and wire studs at the relay.



ELR00825-01 Solenoid

Please contact the LabriePlus Parts Center or Service Department at (800) 231-2771 with any questions or for further information.

March 31, 2014 # 14-12