

To: All Distributors, Regional Sales Manager, and National Sales Managers

From: LabriePlus Service

Model: All

Subject: Tailgate cylinder Orifice

Our HD tailgate cylinder HYC00323 utilizes orifice fitting p/n-10384. This orifice is installed in the fitting closest to case end of the cylinder. (See picture below, fitting highlighted in red).



We have identified that there are two different versions of the p/n-10384 orifice fittings that vary in seating depth. Either dimensional orifice will work in standard TG cylinder HYC00320-04, however, only the shorter version of the orifice fitting will work in tailgate cylinder HYC00323, which is a heavier duty cylinder used on CNG powered units.

(See pictures below depicting both styles of orifice fitting p/n-10384).

Please contact the LabriePlus Service Department at **(800) 231-2771 (US)** or **(877) 452-2743 (CAN)** for questions or further information



If you have the HD tailgate cylinder HYC00323 installed, and it is leaking out of the case end orifice fitting it is likely that the longer version of orifice p/n-10384 was installed. To rectify the issue, replace p/n-10384 orifice with orifice fitting p/n- HYF05120 and #08 JIC fitting p/n 217102.

Please contact the LabriePlus Service Department at **(800) 231-2771 (US)** or **(877) 452-2743 (CAN)** for questions or further information

July 5, 2023

#23-12



DRIVE EXCELLENCE™