
To: All Distributors, Regional Sales Manager, and National Sales Managers

From: LabriePlus Service

Model: Automizer, Expert, Minimax

Subject: Follower Roller Maintenance

All Automizer, Expert, and Minimax Models utilize rollers to guide the packer follower panel forward and rearward as the packer moves.

If a unit is set on three pack cycles per dump and services 1000 carts per day, each roller will have moved at least **6000** times in one day!

Lubrication and periodic inspections are crucial to ensure that the rollers are working properly. Labrie recommends lubrication of the rollers on a twice weekly interval, as well as daily inspection. Remote grease lines should be inspected for breaks or obstructions that would prevent grease from reaching rollers.

Rollers or roller assemblies should be replaced when there is noticeable wear or play in the assembly. Replacement intervals vary greatly with route density, Multicycle settings, and lubrication frequency.

Failure to lubricate, inspect, and replace can result in damage to the front bulkhead from worn rollers.

Please contact your FSR or the Field Service Manager for any questions, or call 1-800-231-2771.

Please contact the LabriePlus Service Department at **(800) 231-2771 (US)** or **(877) 452-2743 (CAN)** for questions or further information